NO: IM1(10)83/12535

Dt:3-11-86

CLICULAR NO. 161.

No.EM1(10)83/2674 dt.19.5.83 and circular No.61 issued under this office No.EM1(10)83/6022 dt.18.8.04 instructions were issued that CEs/SEs/EEs should inspect the work frequently in order to ensure that the works are executed in accordance with design and specification laid down for the works. It was further instructed that copies of inspection note of inspecting officer and action taken in compliance with the instructions should be available at site of work. CE(QC), while inspecting works, had observed that inspection registered of senior officers were blank which means that SEs & CEs have not inspected the works. The site order books have also not been reviewed by IEs. This indicates lack of control of supervision.

It is again enjoined upon all the CEs, SEs & EEs that they must inspect the works as frequently as possible and issue inspection notes/record in the site order book

their observations to ensure that quality of works is executed in accordance with design and specifications laid down for the works.

1. All C.Es, DDA

2. All S.Es, DDA

3. All E.Es, DDA.

Engineer Member