ANNEXURE-VII PART-III

(Serial 1 to 7 are repeat in formation for proper linkage)

1. Period:

2. Name & address of contractor:

M/s. Sharma Construction, U-37,

Mangolpuri, Delhi-83

3. Class, Category and Enlistment No.

III B&R(Civil)

4. Name & address of Enlisting Authority: DDA

5. Name of work:

D/o land at Dwarka Project, Phase-I. SH: C/o parking along 45m R/W road in

sector 11 & 12 at Dwarka.

6. Agreement No.

5/EE/WD-9/DDA/2006-07

7. Name and address of Division

WD-9, DDA, Manglapuri, Dwarka.

11.1	Quality of work	Very good
11.2	Comments on the capabilities of the contractor	Very good
11.2.1	a)Technical Proficiency	Very good
11.2.2	b)Financial soundness	Very good
11.2.3	c)Mobilization of adequate T & P	Very good
11.2.4	d)Mobilization of Manpower	Very good
11.2.5	e)General behavior	Out standing

Executive Engineer Western Division-9 Delhi Development Authority

Reporting Officer

11.1	Quality of work	Very good
11.2	Comments on the capabilities of the contractor	Very good
11.2.1	a)Technical Proficiency	Very good
11.2.2	b)Financial soundness	Very good
11.2.3	c)Mobilization of adequate T & P	Very good
11.2.4	d)Mobilization of Manpower	Very good
11.2.5	e)General behavior	Very good

Reviewing Officer

Er. Lakhvinder Chaudhary Suptdg Engineer C. C.-13/10WK., DDA



ANNEXURE-VII PART-III

(Serial 1 to 7 are repeat information for proper linkage)

1.	Period: 2008-09	
2.	Name & address of contractor :	M/s.Sharma Construction, U-37,
3.	Class, Category and Enlistment No.	Mangol Puri, Delhi-83. III B&R (Civil)No.32/2001
4.	Name & address of Enlisting Authority:	DDA
5.	Name of work	Protection of land at Dwarka Ph-1 SH: Protection of vacant land near
		Secondary school & LSC near group
6.	Agreement No.	Housing Society, Plot No.7, Sec.7, Dwk. 6/EE/WD-8/DDA/2008-09.
7.	Name & Address of Division	WD-8, DDA, Central Nursery, Sector-5, Dwk

11.1	Quality of work	Very good
11.2	Comments on the capabilities of the contractor	Very good
11.2.1	a)Technical Proficiency	Good
11.2.2	b)Financial soundness	Very good
11.2.3	c) Mobilization of adequate T & P	Very good
11.2.4	d)Mobilization of Manpower	Very good
11.2.5	e)General behavior	Out standing

Executive Engineer
Western Division-8
Reporting Officer

12.1	Quality of work	Very good
12.2	Comments on the capabilities of the contractor	Very good
12.2.1	a) Technical Proficiency	Very good
12.2.2	b)Financial soundness	Very good
12.2.3	c)Mobilization of adequate T & P	Very good
12.2.4	d)Mobilization of Manpower	Very good
12.2.5	e)General behavior	Very good.
	1	

Reviewing Office polds. Engineer C. C.-13/ Dwk., DDA