

**DELHI DEVELOPMENT AUTHORITY  
OFFICE OF THE CHIEF ENGINEER(DWARKA)  
MANGLAPURI: NEW DELHI-110045**

No:CE(DWK) 12(6) 11/9741

Dated: 9/12/11

The Secretary  
C.R.B., DDA  
Vikas Minar  
New Delhi-110002.

Sub:- Inspection of works executed by Sh. Manoj Saini who has applied for enlistment as Class-V (Civil) I DDA.

Ref:- Your letter No. F4(8)68/22/2011/V(Civil)Secy/770 dated dated 25.11.11.

Please refer the above mentioned letter vide which undersigned was appointed to inspect the works executed by Shri Manoj Saini RZ-673/1, Gali No. 27 A, Saini Pura, Sadh Nagar, Palam Colony, New Delhi-110045.

The work of upgradation and aesthetic improvement face of building on Maulana Azad Road prior of beginning of Common Wealth Games 2010. SH:- Cleaning of external stone walls face to National Museum Building executed by Shri Manoj Saini was inspected by the undersigned on 3.12.11 and quality of works found satisfactory.

Submitted for further necessary action.

ASR B 3  
9/12

Sd/- Manoj Saini

Manoj Saini  
9/12/11

Manoj Saini  
9/12/11  
SE(HQ)DWK/  
DDA

Govt. of India  
Office of the Superintending Engineer  
Vigyan Bhawan Circle, CPWD,  
Vigyan Bhawan Annexe, New Delhi

22

Confidential

No. 59(1)/VBC/AE(MIS)/2011-12/ 67

Dated : 3/11/11

To

The Secretary,  
Contractor's Registration Board  
Delhi Development Authority  
1<sup>st</sup> Floor, Vikas Minar  
New Delhi.

अध्यक्ष, ठेकाई वजीर बोर्ड,

Secretary. (CRB)

प्रसाद संख्या... 9.8/...

By No. ....

दिनांक... 04-11-11

Date...

**Sub: - Application for revalidation of enlistment in respect of Sh. Manoj Saini.**


Enclosed please find herewith the performance report of Shri Manoj Saini in the appropriate proforma (Annexure-IV) for the following work for taking further necessary action at your end.

- 1) The upgradation and aesthetic improvement facade of building on Maulana Azad Road prior to beginning of Common Wealth Games 2010 (SH: Cleaning of external stone walls face to National Museum Building).


**Agreement No.: 11/EE/VBD/2010-11**

This issues with the approval of Superintending Engineer, Vigyan Bhawan Circle, CPWD.

Encl.: As above.

  
Assistant Engineer (MIS)  
Vigyan Bhawan Circle  
CPWD, New Delhi

A3/CRB 8/11/11

  
Manoj Saini  
19/11/11

M.O.W! - The upgradation and aesthetie improvement facade of building on manlana Azad Road prior to begining of Common wealth Games (SH! - Cleaing of extenal well's face of Natnral Museum).

## ANNEXURE - IV

## CLIENT's CERTIFICATE REG. PERFORMANCE OF CONTRACTOR

Name &amp; Address of the Client

Manoj Saini

Details of Works executed by Shri / M/s

Manoj Saini

R2673/1 St No-27 South Nagar Palam  
Colony New Delhi - 110045

1.	Name of work with brief particulars	SH! - Cleaing of extenal stone well face of natnral museum Bulding
2.	Agreement No. and date	11/EE/VBD/2010-11
3.	Agreement amount	7,48,518/-
4.	Date of commencement of work	31/5/2010
5.	Stipulated date of completion	30/7/2010
6.	Actual date of completion	25/9/2010
7.	Details of compensation levied for delay (indicate amount) if any	Mo — (EOT granted without levy)
8.	Gross amount of the work completed and paid	7,37,750/-
9.	Name and address of the authority under whom works executed	CPWD (Vigyan Bhawan) New Delhi
10.	Whether the contractor employed qualified Engineer / Overseer during execution of work?	— yes —
11.	i) Quality of work (indicate grading) ii) Amt. of work paid on reduced rates, if any.	Outstanding / Very Good / Good / Satisfactory / Poor
12.	i) Did the contractor go for arbitration? ii) If yes, total amount of claim iii) Total amount awarded	— Mo —

20

Name & Address of the Client

Manoj Saini

Details of Works executed by Shri / M/s

Manoj Saini

RZ 673/1, St No- 27, Sadh Nagar Bldm.  
Colony New Delhi - 110045.

13.	Comments on the capabilities of the contractor.	
a)	Technical proficiency	Outstanding / Very Good / Good / Satisfactory / Poor
b)	Financial soundness	Outstanding / Very Good / Good / Satisfactory / Poor
c)	Mobilization of adequate T&P	Outstanding / Very Good / Good / Satisfactory / Poor
d)	Mobilization of manpower	Outstanding / Very Good / Good / Satisfactory / Poor
e)	General behavior	Outstanding / Very Good / Good / Satisfactory / Poor


Note : All columns should be filled in properly  
"Countersigned"

ps   
2.10.11

Officer of the rank of Superintending Engineer or equivalent

अधीक्षण इंजीनियर  
विज्ञान भवन रिमंडल  
कै.लॉ.नि.वि. नई दिल्ली

Signature of the Reporting  
Officer with Office Seal

20/10/11  
  
कार्यपालक अभियन्ता  
विज्ञान भवन मंडल  
कै.लॉ.नि.वि. नई दिल्ली  
नई दिल्ली